

## **METHOD FOR PROVIDING A SMOOTH WAFER SURFACE**

### **ABSTRACT**

5

A method for providing a smooth wafer surface. The technique includes formulating an abrasive mixture by mixing diamond particles and silica particles in a solution based on a predetermined diamond/silica volume ratio mixing diamond particles, and polishing a surface of the wafer with the abrasive mixture to obtain a desired smoothness.

10